

Contact person in HQ, Hamburg:	Ralf Teichmann
Phone:	+494053801-667
Email:	teichmann.r@eppendorf.de

## **Neue Software Version 3.5.1.0 für die BioSpectrometer Familie 613x und BioPhotometer D30 6133 verfügbar**

Für die BioSpectrometer Familie 613x und das BioPhotometer D30 6133, steht eine weitere neue Software Version zum Herunterladen auf der [www.eppendorf-support.com](http://www.eppendorf-support.com) zur Verfügung.

Mit der Software Version 3.5.0.0 kam es bei einigen Geräten zu einem System Fehler (No response from spectrometer unit) und die Xenon Lampe wurde zeitweise nach dem Einschalten nicht angesteuert.

Mit dieser Software Version 3.5.1.0 wird dieser Fehler beseitigt. Die Anweisung zum Installieren der Software finden Sie ebenfalls auf der [www.eppendorf-support.com](http://www.eppendorf-support.com).

## **New software version 3.5.1.0 available for the BioSpectrometer family 613x and the BioPhotometer D30 6133**

Another new software version is available for the BioSpectrometer family 613x and the BioPhotometer D30 6133. It can be downloaded at [www.eppendorf-support.com](http://www.eppendorf-support.com).

Some devices using software version 3.5.0.0 encountered a system error (No response from spectrometer unit) and the Xenon lamp was temporarily not activated after power-on.

This error is eliminated in the new software version 3.5.1.0. The instructions for installing the software can also be found at [www.eppendorf-support.com](http://www.eppendorf-support.com).