

Contact person in HQ, Hamburg:	Uwe Krohss
Phone:	+494053801-193
Email:	Krohss.u@eppendorf.de

Mastercycler nexus New Software V3.5.1.0 including error list

The new nexus Software V 3.5.1.0 including the error listing is now available on our support website www.eppendorf-support.com.

Main reason for this version was error 219 in together with error 635 open lid while program running.

Beside that error listing a "Real time error listing" is available on the Support.com, too. This "Real time error listing" will be updated from us if necessary.

Mastercycler nexus Neue Software V3.5.1.0 inklusive Fehlerliste

Die neue nexus Software V 3.5.1.0 inklusive der Fehlerliste ist jetzt auf unserer Support-Webseite www.eppendorf-support.com verfügbar.

Der Hauptgrund für diese Version war der Fehler 219 im Zusammenhang mit Fehler 635, offener Heizdeckel während eines Programmlaufs.

Neben der Fehlerliste die zusammen mit dem Software Download verfügbar ist, gibt es eine „Real time error listing“ auf der Support.com. Diese „Real time error listing“ wird immer dann aktualisiert wenn es nötig ist.